

Office: Executive Engineer, Provincial Divisional Public Works Department
Building and Roads Branch, Mansa.


Telephone /Fax : 01652-232119
There is a sheep. 665

Email ID: xen.mansa@gmail.com
Date: 21/05/25

Principal,
Kalpana Chawla Memorial Public School,
DHARAMPURA (Mansa)

Subject: -Building Safety Certificate (Year 2025-26)

Havala : Ref. KCM/290 dated 05/04/25 has been sent to me.



Your school building has been visually inspected by the Sub Divisional Engineer's office and as per their report / recommendation, School Building Safety Certificate for the year 2025-26 dated 31-03-2026 subject to the following inspections and conditions.

- 1) Thus, the Structure Safety Certificate has been given by Manish Kumar Jindal on 22-04-2025 and as per his certificate, the school is safe for use for the session 2025-26, but this school has not been constructed by this department. Therefore, the safety of the school structure, especially from the point of view of the school, cannot be ensured by this department.
- 2) Never again will a team be reborn on a day when the daughter of a mother, who was born in the evening, will be left with a chain of chains, and an immediate inspection should be arranged and after completing that part, its safety certificate should be obtained again from this office.
- 3) If the walls, foundation and foundation of the building subside due to a natural disaster or any other reason, then in this case, the school should immediately inform this office about the condition of the building and the building should be put into use only after an inspection.
- 4) Fire safety and electrical safety certificates should be obtained separately from the concerned department.
- 5) Keeping the safety of the school building in mind, it is the responsibility of the school management to get the building repaired. Despite this report, the school management is responsible for the safety of the building from all aspects.
- 6) The school should have a plan to deal with any untoward incident, including the safe evacuation of children from the building during an emergency and coordination with the relevant department. The school should regularly review and update this plan to ensure its effectiveness.
- 7) As per the instructions of the Punjab Government, the school administrator himself will be responsible for obtaining approval for road to access from the concerned department.
- 8) The school must provide appropriate safety training to staff members, including procedures for handling emergencies, first aid, and evacuation protocols.
- 9) Five thousand rupees (5,000/-) received as building inspection fee vide G.R. No. 4828737 dated: 07/05/2025 as per the covered area of the school.
- 10) This report is not valid for legal purposes.

Certified to be true correct &
faithful translation into English
and the original in...

Executive Engineer,
Provincial Divisional B & M Branch
Mansa

Back number no.

A copy of the above is sent to the Sub-Divisional Engineer, Provincial Sub-Division Budhlada in connection with his letter No. 53 dated 09/05/2025 and it is written that keeping in mind your recommendation, a Building Safety Certificate is issued to the said school.

ATTESTED
Ranjeet Singh Khudal
NOTARY PUBLIC BUDHLADA

Executive Engineer,
Provincial Divisional B & M Branch,
Mansa

ਵੱਲ,

Principal,

Kalpna Chawla Memorial PUBLIC School,

DHARAMPURA (Mansa).

ਵਿਸ਼ਾ: ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ। (ਸਾਲ 2025-26)

ਹਵਾਲਾ: ਆਪ ਦਾ ਰੈਫ. ਨੰ. KCM/290 ਮਿਤੀ 05/04/25 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਤੁਹਾਡੇ ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੇ ਦਫਤਰ ਵੱਲੋਂ ਵਿਜ਼ੁਅਲੀ ਇੰਸਪੈਕਸ਼ਨ ਕੀਤੀ ਗਈ ਅਤੇ ਉਹਨਾਂ ਦੀ ਰਿਪੋਰਟ/ਸਿਫਾਰਿਸ਼ ਅਨੁਸਾਰ ਨਿਮਨਲਿਖਤ ਨਿਰੀਖਣਾਂ ਅਤੇ ਸ਼ਰਤਾਂ ਅਧੀਨ ਸਾਲ 2025-26 ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 31-03-2026 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

- 1) ਇੰਜ. ਮਨੀਸ਼ ਕੁਮਾਰ ਜਿੰਦਲ ਵੱਲੋਂ ਮਿਤੀ 22-04-2025 ਨੂੰ ਸਟਰੱਕਚਰ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਦਿੱਤਾ ਗਿਆ ਹੈ ਅਤੇ ਉਹਨਾਂ ਦੇ ਸਰਟੀਫਿਕੇਟ ਅਨੁਸਾਰ ਸਕੂਲ ਸੈਸ਼ਨ 2025-26 ਲਈ ਵਰਤੋਂ ਲਈ ਸੁਰੱਖਿਅਤ ਹੈ, ਪਰੰਤੂ ਇਸ ਸਕੂਲ ਦਾ ਨਿਰਮਾਣ ਇਸ ਵਿਭਾਗ ਵੱਲੋਂ ਨਹੀਂ ਕੀਤਾ ਗਿਆ ਹੈ, ਇਸ ਲਈ ਇਸ ਵਿਭਾਗ ਦੁਆਰਾ ਸਕੂਲ ਦੇ ਸਟਰੱਕਚਰ ਦੀ ਸੇਫਟੀ ਖਾਸ ਕਰਕੇ ਭੂਚਾਲ ਦੇ ਦ੍ਰਿਸ਼ਟੀਕੋਣ ਤੋਂ ਯਕੀਨੀ ਨਹੀਂ ਬਣਾਈ ਜਾ ਸਕਦੀ ਹੈ।
- 2) ਜੇਕਰ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵਾਧਾ, ਤਬਦੀਲੀ, ਵਿਸਤਾਰ ਅਤੇ ਸੋਧ ਦੀ ਲੋੜ ਹੈ ਜਾਂ ਕੀਤੇ ਜਾਣੇ ਹਨ ਤਾਂ ਇਸ ਦਫਤਰ ਦੀ ਤੁਰੰਤ ਜਾਂਚ ਦਾ ਪ੍ਰਬੰਧ ਕੀਤਾ ਜਾਣਾ ਚਾਹੀਦਾ ਹੈ ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।
- 3) ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਧਾਂ, ਨੀਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫ਼ਤ ਜਾਂ ਕਿਸੇ ਹੋਰ ਕਾਰਨ ਕਰਕੇ ਬੈਠ ਜਾਣ ਤਾਂ ਇਸ ਸੂਰਤ ਵਿੱਚ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਦਫਤਰ ਨੂੰ ਤੁਰੰਤ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਲਿਆ ਜਾਵੇ।
- 4) ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਵੱਖਰੇ ਤੌਰ ਤੇ ਫਾਇਰ ਸੇਫਟੀ ਅਤੇ ਬਿਜਲੀ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਪ੍ਰਾਪਤ ਕੀਤਾ ਜਾਵੇ।
- 5) ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਸੇਫਟੀ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੇਅਰ ਕਰਵਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਦੀ ਹੈ। ਇਸ ਰਿਪੋਰਟ ਦੇ ਬਾਵਜੂਦ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਸਾਰੇ ਪੱਖਾਂ ਤੋਂ ਬਿਲਡਿੰਗ ਦੀ ਸੁਰੱਖਿਆ ਲਈ ਜ਼ਿੰਮੇਵਾਰ ਹੈ।
- 6) ਸਕੂਲ ਕੋਲ ਕਿਸੇ ਅਣਸੁਖਾਵੀਂ ਆਪਦਾ ਨਾਲ ਨਜਿੱਠਣ ਲਈ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਦੌਰਾਨ ਬੱਚਿਆਂ ਨੂੰ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਸੁਰੱਖਿਅਤ ਬਾਹਰ ਕੱਢਣਾ ਅਤੇ ਸਬੰਧਤ ਵਿਭਾਗ ਨਾਲ ਤਾਲਮੇਲ ਕਰਨ ਦੀ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ। ਸਕੂਲ ਨੂੰ ਇਸ ਯੋਜਨਾ ਦੀ ਪ੍ਰਭਾਵਸ਼ੀਲਤਾ ਨੂੰ ਯਕੀਨੀ ਬਣਾਉਣ ਲਈ ਨਿਯਮਿਤ ਤੌਰ 'ਤੇ ਸਮੀਖਿਆ ਅਤੇ ਅੱਪਡੇਟ ਕਰਦੇ ਰਹਿਣਾ ਚਾਹੀਦਾ ਹੈ।
- 7) ਪੰਜਾਬ ਸਰਕਾਰ ਦੀਆਂ ਹਦਾਇਤਾਂ ਮੁਤਾਬਕ ਰੋਡ ਟੂ ਅਸੈਸ ਦੀ ਮੰਨਜ਼ੂਰੀ ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਲੈਣ ਲਈ ਸਕੂਲ ਪ੍ਰਬੰਧਕ ਖੁਦ ਜ਼ਿੰਮੇਵਾਰ ਹੋਵੇਗਾ।
- 8) ਸਕੂਲ ਨੂੰ ਸਟਾਫ਼ ਮੈਂਬਰਾਂ ਨੂੰ ਉਚਿਤ ਸੁਰੱਖਿਆ ਸਿਖਲਾਈ ਪ੍ਰਦਾਨ ਕਰਨੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ, ਫਸਟ ਏਡ ਅਤੇ ਨਿਕਾਸੀਪ੍ਰੋਟੋਕੋਲ ਨੂੰ ਸੰਭਾਲਣ ਦੀਆਂ ਪ੍ਰਕਿਰਿਆਵਾਂ ਵੀ ਸ਼ਾਮਲ ਹਨ।
- 9) ਸਕੂਲ ਦੇ ਕਵਰਡ ਏਰੀਏ ਦੇ ਹਿਸਾਬ ਨਾਲ ਜੀ.ਆਰ ਨੰ. 4628737 ਮਿਤੀ: 07/05/2025 ਰਾਹੀਂ ਪੰਜ ਹਜ਼ਾਰ ਰੁਪਏ (5,000/-) ਬਿਲਡਿੰਗ ਨਿਰੀਖਣ ਫੀਸ ਵਜੋਂ ਪ੍ਰਾਪਤ ਕੀਤੇ ਗਏ।
- 10) ਇਹ ਰਿਪੋਰਟ ਕਾਨੂੰਨੀ ਉਦੇਸ਼ ਲਈ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।

ਨੱਥੀ: ਨਕਸ਼ਾ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।
ਮਿਤੀ

ਪਿੱਠ ਅੱਕਣ ਨੰ.

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਬੁਢਲਾਡਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 53 ਮਿਤੀ 09/05/2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਿਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ